

Front Compartment Upper Side Rail Sectioning

Removal Procedure

Caution: Refer to [Approved Equipment for Collision Repair Caution](#) in the Preface section.

Important: Section in specified areas only. Sectioning outside of these areas may compromise the structural integrity of the vehicle. The front compartment upper side rail may be replaced at the factory seams, but requires removal of the front door hinge pillar. This sectioning procedure has been developed as a more cost effective alternative to complete panel replacement


1. Disable the SIR system.

Caution: Refer to Battery [Disconnect Caution](#) in the Preface section.

2. Disconnect the negative battery cable.
3. Remove all related panels and components.
4. Repair as much of the damage as possible to the factory specifications. Refer to [Dimensions - Body](#) .


Caution: Refer to [Foam Sound Deadeners Caution](#) in the Preface section.

5. Note the location and remove all the sealer and anti-corrosion materials from the repair area as necessary. Refer to [Anti-Corrosion Treatment and Repair](#) .




Important: Do not damage any inner panels or reinforcements.


6. At the hinge pillar to upper side rail seam (1), measure 25 mm forward and mark a line following the seam.



7. Cut the upper side rail (1) at the location indicated.




8. Locate and drill out all factory welds on the upper side rail (1). Note the number and location of the welds for installation of the service part.




9. Remove the damaged upper side rail section (1).


[Installation Procedure](#)




1. On the original upper side rail (1), cut and remove 20 mm from the flanges and 5 mm from the center radius



2. Step the tabs (1) inward to allow the upper side rail service to fit over the original upper side rail.




3. On the service upper side rail (1), measure approximately 30 mm from locating hole rearwards and mark a vertical line to overlap to the stepped section of the original rail.




Important: If the location of the original spot weld locations cannot be determined, space the plug weld holes every 40 mm.


4. Drill 8 mm (5/16 in) plug weld holes in the service part as necessary in the locations noted from the original panel.
5. Prepare all mating surfaces as necessary.
6. Apply GM approved weld-thru coating or equivalent to all mating surfaces. Refer to [Anti-Corrosion Treatment and Repair](#) .



7. Position the upper side rail to the vehicle (1) using 3-dimensional measuring equipment. Clamp the rail in place.



8. Plug weld accordingly (1).



Important: To create a solid weld with minimum heat distortion, make a 25 mm stitch weld along the seam with 25 mm gaps between them.

9. Complete the stitch weld (1).
10. Clean and prepare all welded surfaces.
11. Install all related panels and components.
12. Apply the sealers and anti-corrosion materials to the repair area as necessary.
Refer to [Basecoat/Clearcoat Paint Systems](#) .
13. Paint the repair area. Refer to [Basecoat/Clearcoat Paint Systems](#) .
14. Connect the negative battery cable.
15. Enable the SIR system.